

PRACTICE EXAM 12: ASE T2

SIMULATION

DOMAIN A — GENERAL ENGINE DIAGNOSIS (Questions 1–11)

1. A driver reports that his heavy-duty diesel has been producing a loud knock under load for the past week. Before diagnostic testing, the technician should FIRST:

- A. Replace the rod bearings as a precaution
- B. Verify the complaint by road-testing the vehicle under load
- C. Change the engine oil
- D. Disconnect the batteries to reset the ECM

2. A Class 8 tractor returns to the shop for the third time with the same complaint of low power. Previous repairs replaced the turbocharger, DPF, and fuel filter. The appropriate next step is:

- A. Replace the engine ECM
- B. Replace all injectors
- C. Review the full diagnostic history and verify ECM calibration is current
- D. Return the truck as unrepairable

3. Oil analysis shows iron rising from 18 to 92 ppm over two consecutive samples with copper and aluminum trending normally. This pattern MOST likely indicates:

- A. Accelerated wear of ferrous components such as liners, camshafts, or gears
- B. Normal additive depletion

- C. Dirt ingestion through the intake
- D. Coolant contamination

4. A cylinder cutout test shows cylinder 5 producing 8 RPM drop when disabled while other cylinders produce 25 RPM drops. This result indicates:

- A. Normal variation
- B. Cylinder 5 is over-contributing
- C. A scan tool malfunction
- D. Cylinder 5 is weak and requires further diagnosis

5. A driver reports his engine stalls intermittently. Stored DTCs include multiple electrical codes affecting different systems. The MOST likely common cause is:

- A. A failed ECM
- B. Corroded or loose ground connections
- C. A discharged battery
- D. A failed alternator

6. An EGR cooler internal leak allowing coolant into the exhaust recirculation path typically presents first as:

- A. Gradual coolant consumption without visible external leaks
- B. Immediate engine overheating
- C. Black exhaust smoke
- D. Elevated fuel consumption

7. Freeze frame data from a scan tool captures:

- A. Coolant freezing temperature
- B. Battery voltage history
- C. Calibration version information
- D. Engine parameters at the moment a DTC was first set

8. A heavy-duty diesel produces white smoke from the exhaust that persists after warmup and intensifies under load. The MOST likely cause is:

- A. Normal cold-start behavior
- B. Worn piston rings
- C. Coolant entering the combustion chamber from a head gasket or cracked head
- D. Low cetane fuel

9. A Class 8 tractor has been derated to 5 mph with inducement countdown active. This condition is specifically triggered by:

- A. A persistent emissions-related fault in the aftertreatment system
- B. Low engine oil pressure
- C. A discharged battery pack
- D. Transmission failure

10. A repeated no-start condition on a heavy-duty diesel has been verified. Battery voltage is adequate and cranking speed is normal. Rail pressure during cranking reaches only 1,200 psi (spec minimum 3,500 psi). The MOST likely cause is:

- A. Failed accelerator pedal position sensor

- B. Inadequate fuel supply or high-pressure pump wear
- C. Failed alternator
- D. Low ambient temperature

11. Oil sample analysis shows elevated fuel dilution at 6%. This reading indicates:

- A. Normal operation
- B. Improved oil performance
- C. Reduced combustion efficiency
- D. Injector leakage, extended idle, or worn fuel pump seals

DOMAIN B — CYLINDER HEAD AND VALVE TRAIN (Questions 12–15)

12. A cylinder head warpage measurement reads 0.009 inches longitudinally. OEM specification is 0.004 inches maximum. The correct action is:

- A. Install with a thicker gasket
- B. Reuse as-is
- C. Resurface within OEM limits if remaining material allows
- D. Ignore the measurement

13. Head bolts on a modern heavy-duty diesel that have been removed should be:

- A. Replaced, as torque-to-yield fasteners cannot be reliably reused
- B. Reused with additional torque
- C. Reused if they appear undamaged
- D. Measured and reused if within length specification

14. Valve lash specification is typically larger for exhaust valves than intake valves because:

- A. Intake valves are smaller
- B. Exhaust valves open longer
- C. Intake valves are electronically controlled
- D. Exhaust valves experience greater thermal expansion

15. A valve rotator has stopped functioning. The consequence if the engine continues operating is:

- A. Improved valve sealing
- B. Localized valve face and seat burning from uneven wear
- C. Reduced oil consumption
- D. Increased spring force

DOMAIN C — ENGINE BLOCK (Questions 16–20)

16. A cylinder liner has been installed and protrusion measurements show 0.002", 0.002", 0.005", and 0.002" around the circumference. Specification is 0.001"–0.005" with 0.002" max variation. The correct action is:

- A. Install the head and torque normally
- B. Add shims to equalize
- C. Continue with assembly
- D. Remove and inspect the counterbore for debris

17. Crankshaft main journal out-of-round is the difference between:

- A. The journal's length and diameter

- B. Journal diameter and bearing diameter
- C. Perpendicular diameter measurements at the same axial position
- D. Axial measurements along the same journal at the same angle

18. A connecting rod with torque-to-yield bolts has been removed for inspection. The rod itself is reusable, but the bolts must be:

- A. Replaced with new TTY bolts
- B. Reused with additional lubrication
- C. Reused with longer threads engaged
- D. Reused if visual inspection shows no damage

19. Piston-to-cylinder clearance on a heavy-duty diesel is typically measured:

- A. At the piston crown
- B. At 90° to the wrist pin axis at a specified height below the crown
- C. Along the wrist pin axis
- D. Anywhere on the skirt

20. A cracked engine block with the crack passing through the main bearing saddle area requires:

- A. Welding and re-machining
- B. Installation of a reinforcement sleeve
- C. Continued operation with monitoring
- D. Block replacement

DOMAIN D — LUBRICATION AND COOLING (Questions 21–26)

21. Low oil pressure at idle that recovers to normal at 1,800 RPM is the classic signature of:

- A. Worn main or rod bearings producing excessive clearance
- B. A failed oil pump
- C. A stuck-closed pressure relief valve
- D. Incorrect oil viscosity

22. A coolant sample tested with a refractometer shows a freeze point of +10°F. The truck operates year-round in a climate reaching -25°F. The correct action is:

- A. Add tap water
- B. Ignore the reading
- C. Drain and refill with the correct glycol concentration
- D. Install a block heater only

23. Oil-in-coolant contamination without reverse contamination (no coolant-in-oil) MOST commonly indicates:

- A. Head gasket failure
- B. Oil cooler internal leak
- C. Cracked cylinder head
- D. Worn piston rings

24. Engine oil running 10–20°F hotter than coolant temperature at rated load is:

- A. Evidence of oil cooler failure

- B. Evidence of low oil level
- C. Evidence of a stuck thermostat
- D. Normal thermal behavior

25. Supplemental coolant additive (SCA) is added to nitrated heavy-duty coolants to:

- A. Reduce the freeze point
- B. Clean the cooling system
- C. Replenish cavitation inhibitors protecting cylinder liners
- D. Lubricate the water pump

26. A brown emulsion on top of the coolant in the surge tank indicates:

- A. Normal coolant condition
- B. Excessive coolant additive
- C. Internal oil cooler leak with oil migrating into the coolant
- D. Air in the cooling system

DOMAIN E — AIR INDUCTION AND EXHAUST (Questions 27–32)

27. A turbocharger with shaft radial play at 0.035 inches (specification 0.020 max) indicates:

- A. Bearing wear beyond serviceable limits
- B. Normal operation
- C. New turbocharger condition
- D. Thermal expansion only

28. An air intake leak between the filter and turbocharger admits:

- A. Coolant into the compressor
- B. Exhaust into the intake
- C. Oil into the combustion chamber
- D. Unfiltered dust eroding the compressor wheel

29. A VGT stuck in the closed position at high RPM produces:

- A. Reduced boost
- B. Excessive back pressure and potential turbocharger overspeed
- C. Normal operation
- D. Improved fuel economy

30. Exhaust back pressure at rated load on a heavy-duty diesel should normally be below:

- A. 5 psi
- B. 15 psi
- C. 25 psi
- D. 40 psi

31. A charge air cooler contaminated with oil from a failed turbocharger compressor-side seal must be:

- A. Ignored
- B. Pressure-tested only
- C. Cleaned or replaced before installing a new turbocharger
- D. Painted on the outside

32. Active DPF regeneration is commanded when:

- A. The engine reaches idle
- B. Ambient temperature falls below freezing
- C. The vehicle stops
- D. Accumulated DPF soot load exceeds the passive regeneration threshold

DOMAIN F — FUEL SYSTEM (Questions 33–48)

33. A heavy-duty diesel HPCR system has rail pressure reaching only 14,000 psi on command of 28,000 psi. Lift pump output measures 32 psi (spec 45–60). The FIRST diagnostic step should be:

- A. Replace all injectors
- B. Investigate the low-pressure supply system for restriction or air ingestion
- C. Replace the high-pressure pump
- D. Update the ECM calibration

34. Technician A says EUI injectors generate pressure through cam-driven plungers. Technician B says HEUI injectors use high-pressure engine oil acting on a hydraulic intensifier. Who is correct?

- A. Technician A only
- B. Technician B only
- C. Neither Technician A nor Technician B
- D. Both Technician A and Technician B

35. A water-in-fuel warning has illuminated. The correct immediate response is:

- A. Safely stop and drain the water from the separator bowl

- B. Replace the fuel filter element
- C. Add an anti-gel additive
- D. Clear the warning and continue driving

36. HPCR injector calibration codes must be programmed into the ECM because:

- A. The codes prevent unauthorized installation
- B. The ECM compensates for individual injector flow characteristics
- C. The codes confirm warranty coverage
- D. The codes activate the injector electronically

37. A pilot injection event on an HPCR engine delivers approximately:

- A. 30 percent of total cycle fuel
- B. 50 percent of total cycle fuel
- C. 2 to 5 percent of total cycle fuel
- D. 85 percent of total cycle fuel

38. A fuel sample shows a cloud point of 22°F. The truck operates in a climate reaching 5°F. Operation without treatment will result in:

- A. Increased cetane
- B. Improved combustion
- C. Wax crystal formation plugging fuel filters
- D. Boiling of the fuel

39. An injector return flow test shows one injector returning 48 mL/min against peer injectors at 15 mL/min. This reading indicates:

- A. Excessive internal injector leakage
- B. Normal operation
- C. Under-fueling condition
- D. A plugged return line

40. On a HEUI system, the Injection Control Pressure (ICP) sensor monitors:

- A. Fuel rail pressure
- B. High-pressure engine oil to injectors
- C. Coolant pressure
- D. Battery voltage

41. Biodiesel B20 introduced to a heavy-duty diesel previously running petroleum diesel may cause:

- A. Improved fuel economy
- B. Increased cetane
- C. Reduced emissions only
- D. Premature fuel filter plugging from dissolved deposits

42. The primary fuel filter on a heavy-duty diesel typically filters at:

- A. 2 microns
- B. 1 micron
- C. 10 to 30 microns nominal

D. 100 microns

43. An HPCR pressure control valve stuck closed produces:

A. Rail pressure climbing to HP pump maximum output

B. Reduced rail pressure

C. Normal operation

D. Improved engine efficiency

44. Technician A says EUI injectors require ECM solenoid control to determine injection timing. Technician B says EUI injectors use cam-driven plunger motion to generate pressure within the injector. Who is correct?

A. Technician A only

B. Both Technician A and Technician B

C. Technician B only

D. Neither Technician A nor Technician B

45. A fuel tank vent blocked by debris will:

A. Improve fuel economy

B. Have no operational effect

C. Develop tank vacuum, progressively starving the engine

D. Increase fuel pressure

46. Fuel temperature affects injection quantity because:

A. Hot fuel ignites at lower temperatures

- B. Fuel density changes with temperature
- C. Cold fuel is harder to inject
- D. Fuel viscosity determines cetane rating

47. A pilot injection is typically delivered:

- A. At TDC exactly
- B. 45 to 60 degrees BTDC
- C. 30 to 40 degrees ATDC
- D. 15 to 25 degrees BTDC to initiate combustion before main injection

48. On a common rail injection system, which component physically stores pressurized fuel between injection events?

- A. The common rail acting as a pressure accumulator
- B. Each injector internally
- C. The pressure control valve
- D. The high-pressure pump

DOMAIN G — STARTING AND CHARGING (Questions 49–52)

49. A heavy-duty diesel cranks slowly. Battery voltage is 12.4V and voltage drop across the positive cable during cranking measures 1.0V (spec 0.5V max). The MOST likely cause is:

- A. Failed starter motor
- B. Discharged batteries
- C. Excessive resistance in the cable or terminals
- D. Failed alternator

50. A parallel-wired battery pack has three batteries at 12.6V and one at 12.1V. The low-reading battery is MOST likely:

- A. Fully charged
- B. Approaching failure with a possible bad cell
- C. Over-charged
- D. Normal variation

51. An AC ripple reading of 850 mV on alternator output (spec below 100 mV) indicates:

- A. One or more failed rectifier diodes
- B. Slipping drive belt
- C. Discharged battery
- D. Failed voltage regulator

52. A starter motor armature spins freely but does not crank the engine. The MOST likely cause is:

- A. Discharged battery
- B. Failed regulator
- C. Blown fuse
- D. Worn starter drive or pinion

DOMAIN H — ENGINE BRAKES (Questions 53–55)

53. Compression-release engine brakes use engine oil pressure to:

- A. Lubricate the brake housing only
- B. Hydraulically actuate the master and slave piston circuit
- C. Cool the brake mechanism
- D. Monitor brake status electronically

54. An exhaust brake produces braking effort by:

- A. A butterfly valve restricting exhaust flow to create back pressure
- B. Opening exhaust valves near TDC
- C. Activating the alternator
- D. Reducing fuel injection quantity

55. Dashboard brake level switches labeled LOW, MEDIUM, HIGH typically control:

- A. Exhaust temperature limits during braking
- B. Transmission gear selection
- C. The number of cylinders activated for braking
- D. Engine RPM ceiling during braking

PRACTICE EXAM 12: ANSWER KEY AND EXPLANATIONS

1. B — Verifying the complaint under actual operating conditions is always the first step in heavy-duty diesel diagnosis. Road-testing the vehicle under load reproduces the specific conditions the driver described, confirming the symptom and capturing live data during the event. Parts replacement before verification frequently leads to misdiagnosis.
2. C — Repeated failed repairs on the same complaint indicate a diagnostic gap rather than hardware issues. Reviewing full diagnostic history and verifying current ECM calibration often reveals that the root cause was never correctly identified or that a calibration update addresses the condition. This systematic approach saves unnecessary parts replacement.
3. A — Iron climbing from 18 to 92 ppm in consecutive samples represents accelerated wear of ferrous components — typically cylinder liners, camshafts, or gear drives. Normal additive depletion does not produce this rate of increase, and silicon would be elevated with dirt ingestion. Immediate investigation prevents progression to component failure.
4. D — A cylinder producing only 8 RPM drop when others produce 25 RPM drops is contributing significantly less than neighbors. The cylinder was weak before cutout, so disabling it produces minimal additional change. Further diagnosis — compression testing and injector evaluation — is needed to isolate the fault.
5. B — Multiple electrical DTCs affecting different systems simultaneously typically point to a shared fault such as corroded or loose ground connections. Ground problems produce erratic symptoms across systems that share those ground paths. Individual component failures would not produce multi-system symptoms.
6. A — EGR cooler internal leaks typically present first as gradual coolant consumption without visible external leaks. The coolant vaporizes in the hot exhaust stream and leaves through the tailpipe, producing no visible puddles. This is why EGR cooler failures often go undiagnosed for extended periods.
7. D — Freeze frame data captures engine parameters — RPM, load, temperatures, pressures — at the exact moment a DTC was first detected. This contextual information is often more diagnostically valuable than the DTC itself, identifying the conditions under which the fault occurred.

8. C — White smoke that persists after warmup and intensifies under load indicates coolant entering the combustion chamber. The coolant vaporizes to water vapor (visible as white smoke) during combustion. Common sources are head gasket failure, cracked head, or EGR cooler internal leak.
9. A — Inducement countdown on a derated Class 8 tractor is specifically an emissions-related enforcement action. The ECM has detected a persistent fault in the aftertreatment system (typically SCR or DEF-related) and is progressively limiting engine operation per EPA requirements. Other listed conditions do not trigger inducement.
10. B — With adequate battery and cranking speed, rail pressure reaching only 1,200 psi against a 3,500 psi minimum points to a fuel supply problem or HP pump wear. Either inadequate low-pressure supply is preventing the HP pump from building pressure, or the HP pump itself has worn beyond its ability to produce commanded rail pressure.
11. D — Fuel dilution at 6% is substantially above normal levels. Primary causes include injector leakage (fuel dripping past the nozzle between events), extended idle operation (incomplete combustion washing fuel down cylinder walls), or worn fuel pump seals allowing fuel into the crankcase.
12. C — Warp of 0.009 inches against a 0.004-inch specification requires resurfacing within OEM limits. If total material removal stays within the manufacturer's maximum, the head can be restored. Installing with thicker gaskets or ignoring warp produces combustion leaks and gasket failures.
13. A — Modern heavy-duty diesel head bolts are almost universally torque-to-yield (TTY) fasteners. They are stretched past their yield point during installation and cannot reliably produce correct clamping force when reused. Replacement is the OEM-required practice regardless of visual appearance or measured length.
14. D — Exhaust valves operate at significantly higher temperatures than intake valves because they are exposed to hot combustion gases exiting the cylinder. Greater thermal expansion requires larger cold-lash clearance so the valve can fully seat at operating temperature. Intake valve size and electronic control are not factors.
15. B — Valve rotators distribute wear evenly by rotating the valve slightly with each opening. Without rotation, the same portion of the valve contacts the same portion of the seat repeatedly, producing localized burning and uneven wear that leads to valve failure. Replacement of the rotator is required.
16. D — Three readings at 0.002" and one at 0.005" exceed the 0.002" maximum variation specification, even though individual values fall within the range. The uneven protrusion indicates debris, damage, or an uneven counterbore that must be corrected before head installation to prevent gasket failure.

17. C — Out-of-round is specifically the difference between diameter measurements at perpendicular angles (typically 90°) at the same axial position. This measures cross-sectional shape distortion. Taper — the separate measurement — is the difference between axial positions at the same angle.
18. A — Torque-to-yield rod bolts must be replaced when removed, regardless of whether the rod is reusable. TTY bolts have been permanently stretched past their yield point and cannot reliably provide correct clamping force on reuse. Failure of a reused TTY bolt results in catastrophic rod separation and engine destruction.
19. B — Piston-to-cylinder clearance is measured at 90° to the wrist pin axis at a specified height below the piston crown. This location is chosen because it is the most dimensionally significant point for establishing running clearance — where piston thrust occurs and where accurate comparison to specification can be made.
20. D — Structural cracks through the main bearing saddle area are not reliably repairable in commercial heavy-duty diesel service. The forces in this location are too high for weld repair to provide long-term reliability, and stress concentration at crack tips continues to propagate under operation. Block replacement is the correct action.
21. A — Low oil pressure at idle that recovers at higher RPM is the classic signature of worn main or rod bearings. As clearance increases from wear, more oil leaks out of the bearings at low pump output (idle); at higher RPM, increased pump output overcomes the leakage to restore pressure.
22. C — A +10°F freeze point in a climate reaching -25°F provides inadequate protection and risks catastrophic freeze damage to the block, head, and heater core. Simply adding antifreeze to a degraded mixture cannot reliably restore protection; drain and refill with correct ratio ensures proper freeze protection.
23. B — Oil-in-coolant without reverse contamination is the classic signature of an oil cooler internal leak. Oil pressure normally exceeds coolant pressure, so internal leaks in the oil cooler flow from high-pressure oil to lower-pressure coolant. Head gasket and block cracks would typically produce bidirectional contamination.
24. D — Engine oil typically runs 10–20°F higher than coolant temperature at rated load. The oil absorbs heat directly from bearings, piston cooling jets, and friction surfaces that operate hotter than the coolant. This thermal relationship is normal and indicates both cooling and lubrication systems are functioning correctly.
25. C — SCA is a nitrite-based additive that replenishes cavitation inhibitor chemistry protecting cylinder liner outer surfaces. Cavitation damage occurs when coolant bubbles form and collapse against liners during cylinder flex; the nitrite forms protective films that prevent this attack. Without SCA, liners develop pitting damage.
26. C — Brown emulsion on top of coolant in the surge tank is the classic signature of an internal oil cooler leak. Oil pressure exceeds coolant pressure, forcing oil into the coolant side where it floats

to the top and forms a visible emulsion layer. The finding directs diagnosis specifically to the oil cooler.

27. A — Shaft radial play nearly double the maximum specification indicates bearing wear beyond serviceable limits. Heavy-duty turbocharger bearings wear from oil supply issues (kinked lines, low pressure), contamination, or extended operation beyond service intervals. Turbocharger rebuild or replacement is required.
28. D — An air intake leak between the filter and turbocharger admits unfiltered dust directly to the compressor wheel. Abrasive particles erode the compressor blade leading edges and damage bearings. This location has no secondary filtration, so the compromise becomes critical to turbocharger service life.
29. B — A VGT stuck closed at high RPM restricts exhaust flow precisely when volume is highest. The result is excessive back pressure, potential turbocharger overspeed, and elevated cylinder pressures that can damage pistons and valves. This condition cannot be tolerated; immediate intervention is required.
30. A — Normal exhaust back pressure at rated load on a heavy-duty diesel is 3 to 5 psi maximum. Values above 5 psi indicate restriction in the exhaust system or aftertreatment. The specification provides the threshold for diagnosis; readings significantly above 5 psi warrant investigation.
31. C — An oil-contaminated CAC will immediately contaminate any new turbocharger installed on the same engine. Residue coats internal surfaces and provides a continuous source of contamination that damages the new turbo's compressor seal. Cleaning or replacing the CAC before turbo installation is essential.
32. D — Active regeneration is commanded when accumulated DPF soot exceeds the threshold that passive regeneration can clear. The ECM then initiates fuel dosing to raise DPF temperature high enough (approximately 1,000–1,200°F) to burn off accumulated soot. Engine speed, ambient temperature, and vehicle stopping are not primary triggers.
33. B — Lift pump output at 32 psi (well below 45–60 spec) indicates inadequate low-pressure supply, which prevents the HP pump from building rated rail pressure. The low-pressure supply must be verified and repaired first before investigating HP components. Parts replacement without addressing the supply issue wastes time and money.
34. D — Both technicians are correct. EUI injectors use cam-driven plungers inside each injector to generate injection pressure locally. HEUI injectors use high-pressure engine oil acting on a hydraulic intensifier inside each injector. These defining characteristics distinguish the two injection technologies.
35. A — A water-in-fuel warning indicates water has accumulated in the separator bowl to the sensor level. Safely stopping and draining the water prevents it from reaching the fuel filter and injection

system, which would cause serious damage. Continuing operation risks expensive fuel system contamination.

36. B — HPCR injectors carry unique factory calibration codes encoding their individual flow characteristics. The ECM uses this code to compensate for injector-to-injector variation during operation. Without proper coding, cylinder balance faults and emissions issues develop because the ECM cannot match actual injector flow to command.
37. C — Pilot injection delivers a small quantity of fuel, typically 2 to 5 percent of total cycle fuel. The small volume is enough to initiate combustion early and raise chamber conditions, reducing ignition delay on the main injection and significantly reducing combustion noise. Main injection delivers 65–85% of total fuel.
38. C — Fuel with a cloud point of 22°F will form wax crystals at any temperature below that value. In a 5°F climate, wax progressively plugs fuel filters, starving the engine. Anti-gel additives or winter blending are required to prevent wax-related operational problems in cold conditions.
39. A — Return flow of 48 mL/min against peers at 15 mL/min represents more than triple the normal leakage rate. This indicates excessive internal leakage past worn plungers or control valves — rail pressure escapes through the return path rather than being delivered as injection. Injector service or replacement is required.
40. B — On HEUI systems, the ICP (Injection Control Pressure) sensor monitors the high-pressure engine oil supplied to the injectors. HEUI injection pressure is generated from this oil acting on each injector's hydraulic intensifier. ICP feedback allows the ECM's pressure control loop to maintain commanded injection pressure.
41. D — Biodiesel acts as a solvent and dissolves accumulated deposits in fuel tanks, lines, and filters. When switching from petroleum diesel to B20, these deposits flush through the system and collect in the fuel filter, causing premature plugging. Filter service intervals should be reduced during the transition period.
42. C — Primary fuel filters on heavy-duty diesels filter at 10 to 30 microns nominal. This coarser filtration captures significant contamination at high flow rates. The finer secondary filter (2–4 microns) provides final protection for high-pressure injection components; primary filters handle initial contamination capture.
43. A — A pressure control valve stuck closed cannot bleed excess rail pressure. The HP pump continues pumping until reaching its maximum output capacity, far exceeding commanded pressure. Modern ECMs detect this overpressure condition and trigger protective derate to prevent catastrophic damage to fuel system components.
44. B — Both technicians are correct. EUI injectors combine cam-driven mechanical plunger motion (generating injection pressure) with ECM solenoid control (determining timing and duration). The

camshaft provides pumping force; the ECM solenoid controls when injection occurs. Both elements are essential to EUI operation.

45. C — A blocked tank vent prevents atmospheric air from entering as fuel is consumed. Vacuum progressively develops in the tank, opposing fuel flow through the pickup. Initially the engine may run at low demand, but the vacuum eventually starves the engine, producing power loss and stalling.
46. B — Fuel density varies with temperature — hotter fuel is less dense than cooler fuel. Because injection is commanded as a volume (duration of valve open time at rail pressure), temperature-driven density changes affect the mass of fuel delivered per injection pulse. Modern ECMs compensate injection timing based on fuel temperature.
47. D — Pilot injection occurs approximately 15 to 25 degrees before TDC to initiate combustion before the main injection arrives. This early combustion raises chamber pressure and temperature, reducing ignition delay on the main event and significantly reducing diesel combustion noise and NOx formation.
48. A — The common rail is the pressurized accumulator that stores fuel between injection events. The HP pump maintains rail pressure; each injector releases stored pressure when commanded. Individual injectors do not store fuel internally, and the pressure control valve regulates rather than stores pressure.
49. C — Cable voltage drop of 1.0V (against 0.5V max) indicates excessive resistance in the positive cable or its terminal connections. Battery voltage is adequate at 12.4V, so the fault is not battery-related. The resistance restricts current flow to the starter, producing slow cranking despite sufficient battery charge.
50. B — A battery at 12.1V in a pack with three others at 12.6V shows lower open-circuit voltage indicating a possible cell failure or significant capacity degradation. The 0.5V difference is substantial and will degrade overall pack performance. Load testing confirms weakness; replacement is recommended.
51. A — AC ripple reading 8.5 times above specification is the classic signature of failed rectifier diodes. Each failed diode allows AC to pass through to the DC output. Elevated ripple damages sensitive electronic components throughout the vehicle, especially ECM circuits. Belt slip and regulator issues produce different symptoms.
52. D — When the starter armature spins freely without cranking the engine, the drive mechanism has failed to transfer rotation to the flywheel ring gear. The pinion, Bendix drive, or shift fork is worn or damaged. Battery, regulator, and fuse issues would prevent armature rotation entirely, not just engagement.
53. B — Compression-release engine brakes use engine oil pressure to hydraulically actuate the master and slave piston circuit. The master piston (driven by a dedicated cam lobe) displaces oil through

the circuit to the slave piston, which pushes the exhaust valve open near TDC. Adequate oil pressure is essential for the mechanism.

54. A — Exhaust brakes use a butterfly valve in the exhaust piping to restrict flow, creating back pressure that the piston must pump against during the exhaust stroke. The pumping work absorbs drivetrain energy. The mechanism is simpler than compression-release brakes but generally produces less braking power per cylinder.
55. C — Dashboard brake levels (LOW, MEDIUM, HIGH) control the number of cylinders activated for compression-release braking. LOW typically engages 2 cylinders, MEDIUM 4, and HIGH all 6 on a six-cylinder engine. Each level adds cylinders to progressively increase braking effort for different driving conditions.