

PRACTICE EXAM 14: ASE L4 SIMULATION (50 QUESTIONS)

1. On the composite vehicle, the forward-facing camera heater activates at an ambient temperature of approximately:

- A. 50°F or 10°C or colder ambient temperature
- B. 32°F or 0°C or colder ambient temperature
- C. 0°F or -18°C or colder ambient temperature
- D. 70°F or 21°C or colder ambient temperature

2. On the composite vehicle, the forward-facing camera bracket is bonded to the interior surface of:

- A. The dashboard top pad near the defrost vents
- B. The headliner at the front of the cabin interior
- C. The A-pillar trim panel on the driver side
- D. The windshield near the interior rearview mirror

3. On the composite vehicle, if the forward-facing camera lens becomes contaminated during service, the required action is:

- A. Replace the camera — the lens cannot be cleaned per the reference
- B. Clean the lens with approved lens cleaner and a microfiber cloth
- C. Apply a new protective coating to the lens during reinstallation
- D. Leave contamination in place if it does not fully obscure the view

4. On the composite vehicle, the private CAN bus connecting the corner radar modules has its primary node designated as:

- A. The right front corner radar at the front of the vehicle
- B. The Gateway Module routing data to the public bus
- C. The left rear corner radar aggregating all corner radar data
- D. The ADAS Central Module acting as the network hub

5. On the composite vehicle, each corner radar module contains a terminating resistor with a specified value of:

- A. 60 ohms for half of the parallel bus resistance
- B. 120 ohms combining in parallel for standard termination
- C. 240 ohms providing double the parallel termination value
- D. 30 ohms compensating for longer wire runs

6. On the composite vehicle, a technician measures the private corner radar CAN bus at 120 ohms instead of the expected 60 ohms. This reading most likely indicates:

- A. Normal operation with both terminators correctly installed
- B. A short between CAN-H and CAN-L at the bus
- C. Complete failure of every module on the private bus
- D. One corner radar has been disconnected or isolated from the bus

7. On the composite vehicle, the forward radar module's maximum detection range is specified at approximately:

- A. 80 meters for short-range urban driving operation

- B. 160 meters for highway-speed ACC and AEB operation
- C. 250 meters for luxury-segment long-range applications
- D. 40 meters for short-range parking radar configurations

8. On the composite vehicle, the forward radar module communicates detected target data primarily to:

- A. The Electronic Power Steering Module for direct steering input
- B. The Gateway Module for diagnostic tool access only
- C. The ADAS Central Module over the public ADAS CAN bus
- D. The Instrument Cluster Module for direct display output

9. On the composite vehicle, after a replacement forward radar module has been programmed and coded, the module cannot be considered operational until:

- A. Static and dynamic calibration per OEM specification are completed
- B. A 48-hour break-in period allows the module to self-learn
- C. Every other ADAS module is reprogrammed with updated firmware
- D. The scan tool verifies communication without any further action

10. On the composite vehicle, the ADAS Central Module's primary architectural role is:

- A. Directly operating the brake hydraulic actuator during AEB events
- B. Hosting the warning chime during lane departure warning events
- C. Receiving sensor inputs, running ADAS logic, issuing output commands
- D. Serving as a backup to the Gateway Module when networks fail

11. On the composite vehicle, the ADAS Central Module receives power from:

- A. Only constant battery voltage with no switched supply
- B. Both constant battery voltage and switched ignition voltage
- C. Only the Gateway Module's switched output supply
- D. Only the Instrument Cluster Module's accessory output

12. On the composite vehicle, during active lane keep assistance, the ADAS Central Module communicates with the Electronic Power Steering Module by:

- A. A dedicated hardwired signal bypassing the CAN network
- B. The private corner radar CAN bus shared with the corner radars
- C. The cellular link routed through the Telematics Control Module
- D. The public ADAS CAN bus using torque request messages

13. On the composite vehicle, the surround view system is composed of a total number of cameras equal to:

- A. 2 cameras — one at the front and one at the rear
- B. 4 cameras — front grille, rear, and both exterior mirrors
- C. 6 cameras — front, rear, and four side positions
- D. 8 cameras — multiple positions around the vehicle's perimeter

14. On the composite vehicle, each surround view camera uses a lens with an angular field of view of approximately:

- A. 20 to 30 degrees for narrow-angle detection
- B. 45 to 60 degrees for medium-angle coverage

- C. 75 to 90 degrees for moderately wide coverage
- D. 180 degrees or more for very wide-angle coverage

15. On the composite vehicle, if an exterior mirror housing that contains a surround view camera is replaced, the required follow-up action is:

- A. Delivering the vehicle immediately without any other action needed
- B. Calibration of the replaced side-view surround view camera
- C. Complete reprogramming of the Surround View Module firmware
- D. Replacement of all four surround view cameras to match

16. On the composite vehicle, the ultrasonic sensors are mounted primarily in:

- A. The front and rear bumper covers at multiple positions
- B. The windshield header near the forward camera location
- C. The exterior mirror housings with the surround view cameras
- D. The center of the dashboard pointing outward through glass

17. On the composite vehicle, the Ultrasonic Control Module communicates aggregated sensor data to the ADAS Central Module through:

- A. A dedicated private CAN bus for only these two modules
- B. A hardwired direct connection bypassing the CAN network
- C. The cellular connection through the Telematics Control Module
- D. The public ADAS CAN bus shared with other ADAS modules

18. On the composite vehicle, the forward-facing camera supports the following group of features:

- A. Adaptive cruise control and emergency braking at highway speeds
- B. Blind spot warning and rear cross-traffic alert systems
- C. Lane departure, lane keep, traffic sign recognition, high beam assist
- D. Ultrasonic parking assist and surround view composite imaging

19. On the composite vehicle, the steering wheel haptic feedback actuator's coil resistance specification is:

- A. 36 ohms with a tolerance of plus or minus 4 ohms
- B. 12 ohms with a tolerance of plus or minus 2 ohms
- C. 100 ohms with a tolerance of plus or minus 10 ohms
- D. 50 ohms with no specified tolerance for the value

20. Enable criteria for a specific DTC are best described as:

- A. The list of parts that must be replaced when the code is observed
- B. The conditions a module must observe before running the monitor
- C. The time limit before the code automatically deletes itself
- D. The sequence in which other modules must be programmed

21. A healthy CAN bus with two 120-ohm terminators in parallel measures across CAN-H and CAN-L with ignition off at approximately:

- A. 0 ohms indicating a direct short between the wires
- B. 120 ohms from only one terminator being present
- C. 60 ohms from the two 120-ohm terminators in parallel

D. 240 ohms from the two terminators added in series

22. Voltage drop testing is more diagnostically sensitive than continuity testing primarily because voltage drop testing:

- A. Is performed with the circuit energized under operating load
- B. Uses a much higher test voltage than continuity testing
- C. Requires specialized equipment beyond a basic multimeter
- D. Measures resistance rather than voltage in the circuit

23. ADAS calibration requires battery voltage to be maintained throughout the procedure at approximately:

- A. Above 10.5 volts as the absolute minimum for module operation
- B. Between 11.5 and 12.5 volts during all calibration procedures
- C. Cycling between 12.0 and 14.5 volts during the procedure
- D. Above 12.6 volts maintained by a battery support unit

24. A pre-repair scan primarily serves to:

- A. Automatically repair all modules that show any stored codes
- B. Document the vehicle's condition before any repair work begins
- C. Reset all existing codes to establish a fresh starting state
- D. Calibrate every ADAS sensor as a diagnostic precaution

25. Silent miscalibration of an ADAS sensor is best described as:

- A. The sensor completely fails and sets an obvious scan tool error

- B. The calibration procedure aborts at the first precondition check
- C. The procedure completes successfully but produces degraded performance
- D. The sensor physically damages itself during the calibration attempt

26. After programming of a replacement forward camera has been completed successfully, the next required step per OEM procedure is:

- A. Static calibration before any other configuration steps
- B. Coding — configuring the module with vehicle-specific parameters
- C. Delivering the vehicle with the programmed module installed
- D. Reprogramming the ADAS Central Module with current firmware

27. Windshield replacement on a vehicle equipped with a forward camera typically requires:

- A. Replacement of the forward camera assembly during the glass service
- B. Installation of an aftermarket protective film in the camera area
- C. Forward camera calibration per OEM position statement guidance
- D. Complete reprogramming of the ADAS Central Module firmware

28. A customer reports that a forward camera feature fails specifically when direct sunlight shines into the camera. The most likely explanation is:

- A. Temporary sun-glare sensitivity — a known camera limitation
- B. Complete failure of the forward camera module requiring replacement
- C. Electronic Power Steering Module interference with the camera
- D. Normal operation that the customer should not notice at all

29. Lane keep assistance differs from lane departure warning primarily because lane keep assistance:

- A. Operates only at speeds below 25 mph on city streets
- B. Provides active steering rather than only an audible alert
- C. Uses ultrasonic sensors instead of the forward-facing camera
- D. Requires the driver to engage the feature manually each time

30. A failed forward camera heater in cold weather most commonly produces the symptom of:

- A. Immediate physical damage to the camera's internal components
- B. Continuous parking assist activation during any cold operation
- C. Failure of ultrasonic sensors despite the unrelated system
- D. Camera fogging or icing that disables camera-dependent features

31. Automotive radar modules used for ADAS applications most commonly operate in which frequency band?

- A. The 2.4 GHz band used by consumer Wi-Fi equipment
- B. The 5.9 GHz band reserved for vehicle-to-vehicle communication
- C. The 76 to 81 GHz band often called 77 GHz automotive radar
- D. The 24 GHz band with limited remaining regulatory allocation

32. The acronym FMCW, used in automotive radar, stands for:

- A. Frequency-Modulated Continuous Wave for range and velocity
- B. Frequency-Matched Continuous Waveform with stepped signal bursts
- C. Fast Modulated Closed Wavelength in narrow-beam applications

D. Free-Modulated Cumulative Wave for high-resolution imaging

33. Adaptive cruise control requires input from which pair of sources at minimum?

- A. The driver monitoring camera and the steering angle sensor
- B. Ultrasonic sensors and the Telematics Control Module
- C. The LiDAR sensor and the Electronic Brake Control Module
- D. The forward radar and the ACC switch inputs on the steering wheel

34. Non-OEM bumper covers with non-OEM paint in the forward radar zone may degrade radar performance because:

- A. Non-OEM covers always include amplifiers that overload the radar
- B. The materials may not meet the required radar transparency specification
- C. Non-OEM covers automatically block the radar module from installation
- D. The paint produces electromagnetic interference at the 77 GHz band

35. On a typical ADAS vehicle, the corner radar modules directly support which pair of features?

- A. Blind spot warning and rear cross-traffic alert systems
- B. Adaptive cruise control and lane keep assistance features
- C. Traffic sign recognition and automatic high beam control
- D. Ultrasonic parking assist and the surround view composite image

36. Silent miscalibration is most often caused by:

- A. Complete internal hardware failure of the sensor module

- B. Scan tool communication loss during the calibration procedure
- C. Power loss during the procedure triggering an abort message
- D. Unverified preconditions during the calibration procedure

37. OEM position statements regarding ADAS repair requirements are best described as:

- A. Promotional material aimed at encouraging dealership service
- B. Technical suggestions that may be followed at technician discretion
- C. Formal OEM guidance defining the standard of care for repairs
- D. Legally binding federal regulations issued by NHTSA authority

38. After programming, coding, and initialization of a replacement radar module, the required final step before delivery is:

- A. Delivering the vehicle without any further procedures required
- B. Performing a dynamic drive without any static procedure
- C. Clearing all codes and considering the workflow complete
- D. Calibration per OEM procedure establishing the geometric reference

39. Ultrasonic sensors used for parking assist operate at frequencies in the range of approximately:

- A. Audible frequencies between 2 and 20 kilohertz for driver alerts
- B. Radio frequency in the 77 GHz automotive radar band
- C. Above human hearing at approximately 40 to 50 kilohertz
- D. In the visible light spectrum with infrared detection

40. The typical maximum effective range of an automotive ultrasonic sensor is approximately:

- A. 2 to 5 meters for low-speed maneuvering applications
- B. Hundreds of meters similar to long-range automotive radar
- C. Tens of meters appropriate for highway-speed target detection
- D. Less than 10 centimeters making contact detection required

41. Paint applied directly over an ultrasonic sensor's transducer face typically causes:

- A. No effect on sensor operation so long as the paint is fully dried
- B. Improved weather sealing of the sensor with no functional downside
- C. Signal attenuation and degraded or failed sensor operation
- D. Temporary disabling that reverses within a few driving cycles

42. A single ultrasonic sensor has been identified as internally failed. The correct service approach is:

- A. Replace every ultrasonic sensor on the vehicle simultaneously
- B. Replace the entire Ultrasonic Control Module with a new unit
- C. Reprogram the Ultrasonic Control Module with current firmware
- D. Replace only the failed sensor and verify operation via scan tool

43. Rear cross-traffic alert on a typical ADAS vehicle relies primarily on which sensor category?

- A. The forward-facing camera at the top of the windshield
- B. Ultrasonic sensors mounted in the rear bumper cover
- C. The rear corner radar modules using the private CAN bus
- D. The forward radar mounted in the front grille area

44. A customer reports that parking sensors fail only in cold weather. The sensors appear clean in the warm shop. The most likely cause is:

- A. Ice or snow accumulation on transducer faces melting before arrival
- B. Complete failure of the Ultrasonic Control Module in cold weather
- C. Reprogramming needed for winter operation of the module
- D. Normal behavior that customers should accept during winter

45. A customer's rear parking sensors produce false activations during rainy weather. In dry conditions the system works correctly. The most likely cause is:

- A. Complete ultrasonic system failure triggered by the rain event
- B. ADAS Central Module malfunction during any precipitation event
- C. Water droplets on transducer faces producing false echo returns
- D. Normal operation during any rain event regardless of duration

46. After a battery disconnection during unrelated service, multiple ADAS features have become unreliable. The most productive action is to:

- A. Replace every affected module as a precaution against battery damage
- B. Check OEM procedures for required relearn procedures for affected modules
- C. Perform a complete four-wheel alignment to reset all references
- D. Reprogram every ADAS module with the current firmware release

47. The post-repair scan's primary purpose compared to the pre-repair scan is to:

- A. Verify which codes cleared and identify any new codes introduced
- B. Replace the vehicle's diagnostic history with the new state

- C. Automate the OEM warranty claim process for the shop
- D. Generate a printed receipt for the customer's service records

48. Operational verification after an ADAS repair primarily confirms that:

- A. The scan tool's software version is the most current release available
- B. The customer will not have any future complaints about the feature
- C. Every unrelated module is functioning within its normal specifications
- D. The repaired feature actually functions under real-world conditions

49. During customer handoff after an ADAS repair, the most important point to communicate is:

- A. The complete list of scan tool codes that appeared in the pre-repair scan
- B. What was repaired, expectations, and that ADAS assists but does not replace the driver
- C. Specific details about each OEM position statement consulted during service
- D. The exact voltage readings measured during each diagnostic step taken

50. ADAS repair documentation should be retained per shop policy for:

- A. Extended periods aligning with insurance and litigation timelines
- B. A maximum of 30 days since older records cannot be accessed
- C. Only until the customer picks up the vehicle after the service
- D. A maximum of 60 days per federal regulation requirements

PRACTICE EXAM 14: ANSWER KEY AND EXPLANATIONS

1. A — The composite vehicle specifies the forward-facing camera heater activation temperature at approximately 50°F or 10°C or colder ambient temperature. This specific value is reference-sourced and commonly tested. The heater also activates when either the front or rear defrost is commanded, providing a dual-trigger condition for maintaining a clear camera view.
2. D — The composite vehicle's forward-facing camera is mounted to a bracket bonded to the interior surface of the windshield near the interior rearview mirror. This universal mounting location is why windshield replacement always disturbs the camera's mounting position and requires subsequent calibration per OEM position statements.
3. A — The composite vehicle specifies that the forward-facing camera lens cannot be cleaned per the reference document; contamination requires camera replacement. Cleaning attempts damage the optical coating and create worse problems than the original contamination, making replacement the only supported response.
4. C — The composite vehicle designates the left rear corner radar module as the primary node on the private corner radar CAN bus. It aggregates data from the four corner radars and forwards the fused result to the ADAS Central Module over the public ADAS CAN bus. This aggregation architecture is commonly tested on the exam.
5. B — Each corner radar module on the composite vehicle contains a 120-ohm terminating resistor. Two 120-ohm terminators in parallel produce the standard 60-ohm resistance measurement across the bus wires, which is the standard CAN termination value used industry-wide.
6. D — A private corner radar CAN bus reading 120 ohms instead of the healthy 60 ohms indicates only one terminator is in the circuit. This typically means one corner radar (containing a terminator) has been disconnected or isolated from the bus, which is the diagnostic signature of a missing module on any CAN bus architecture.
7. B — The composite vehicle specifies the forward radar module's maximum detection range at approximately 160 meters. This specific value distinguishes the composite vehicle's forward radar from shorter-range corner radars and longer-range luxury implementations, and it is a reference-sourced detail frequently tested.
8. C — The composite vehicle's forward radar communicates detected target data to the ADAS Central Module over the public ADAS CAN bus. The ADAS Central Module then processes this

data along with inputs from other sensors before commanding output modules to take appropriate ADAS actions.

9. A — After programming and coding of a replacement forward radar, static and dynamic calibration per OEM specification are required before the module can be considered operational. Calibration establishes the geometric reference that allows the radar to correctly interpret target positions — without it, the radar cannot function correctly regardless of programming status.
10. C — The composite vehicle's ADAS Central Module serves as the central decision-making hub: it receives sensor inputs, runs ADAS algorithms, and issues commands to output modules. It does not directly drive actuators, host warning chimes, or serve as a Gateway backup — those roles belong to their respective modules.
11. B — The composite vehicle's ADAS Central Module receives both constant battery voltage (for standby memory and wake functions) and switched ignition voltage (for active operation). This dual-supply arrangement is standard for ADAS modules on the composite vehicle architecture.
12. D — During active lane keep assistance, the composite vehicle's ADAS Central Module issues torque request messages to the Electronic Power Steering Module over the public ADAS CAN bus. The EPS module translates these requests into commanded current to the steering motor — this request-and-execute architecture is a key architectural feature.
13. B — The composite vehicle's surround view system uses four cameras: one at the front grille, one at the rear, and one in each exterior mirror housing. These four cameras' outputs are stitched together by the Surround View Module into a composite overhead image displayed during low-speed maneuvering.
14. D — The composite vehicle's surround view cameras use very wide-angle lenses with fields of view of approximately 180 degrees or more. This wide coverage is essential so the Surround View Module can stitch four overlapping camera views into a seamless composite overhead image without significant gaps.
15. B — Exterior mirror housing replacement disturbs the mounting of the surround view camera contained in that mirror. Calibration of the replaced camera is required because the Surround View Module's image stitching depends on accurate geometric references from each camera position.
16. A — The composite vehicle's ultrasonic sensors are mounted primarily in the front and rear bumper covers at multiple positions along each fascia. This mounting configuration provides a ring of short-range detection coverage around the vehicle's perimeter and is standard across modern OEM designs.
17. D — The composite vehicle's Ultrasonic Control Module communicates aggregated sensor data to the ADAS Central Module over the public ADAS CAN bus. There is no dedicated private bus, hardwired direct connection, or cellular pathway between these modules — the standard public bus carries this communication.

18. C — The composite vehicle's forward-facing camera supports lane departure warning, lane keep assistance, traffic sign recognition, and automatic high beam assist simultaneously. ACC and AEB rely on the forward radar, while blind spot warning and rear cross-traffic alert rely on corner radars, not the forward camera.
19. A — The composite vehicle specifies the steering wheel haptic feedback actuator coil resistance at 36 ohms with a tolerance of plus or minus 4 ohms. This reference-sourced specification is commonly tested and provides the diagnostic threshold for determining whether a measured resistance reading indicates a functional or failed actuator.
20. B — Enable criteria are the specific conditions a module must observe before running a diagnostic monitor that could set a DTC. Understanding enable criteria explains why faults sometimes do not produce stored codes until the vehicle is driven under matching conditions, which is essential for effective diagnostic verification.
21. C — A healthy CAN bus with two 120-ohm terminating resistors in parallel measures approximately 60 ohms across CAN-H and CAN-L with the ignition off. This is the foundational measurement for verifying CAN bus integrity, and deviation from 60 ohms indicates specific fault conditions that require investigation.
22. A — Voltage drop testing is performed with the circuit energized under operating load, which is what makes it diagnostically sensitive for marginal connections. Load-dependent resistance that only manifests when current flows cannot be detected by continuity or DC resistance tests, making voltage drop testing the preferred method for connection diagnosis.
23. D — ADAS calibration requires battery voltage maintained above 12.6 volts throughout the procedure, typically achieved through a battery support unit. Voltage drops during calibration can cause the procedure to fail mid-execution or produce silent miscalibration, which is why battery support is mandatory equipment for professional ADAS calibration.
24. B — The pre-repair scan documents the vehicle's condition before any repair work begins, establishing the diagnostic baseline for all subsequent activities. This documentation protects the shop from responsibility for pre-existing DTCs and creates the foundation for comparison against the post-repair scan after the work is completed.
25. C — Silent miscalibration is the scenario where the calibration procedure completes successfully on the scan tool but real-world ADAS performance is degraded. It typically results from unverified preconditions (floor slope, vehicle loading, tire pressure, target placement) that the scan tool cannot detect — the procedure saves incorrect parameters while reporting success.
26. B — After programming loads the replacement module's firmware, coding is the next required step because it configures the module with vehicle-specific parameters and feature options. Programming makes the module function generically; coding tells it which specific vehicle it is installed in, enabling features appropriate to that vehicle's configuration.

27. C — Windshield replacement on an ADAS-equipped vehicle with a forward camera requires calibration per virtually every major OEM's position statement. The camera bracket is bonded to the windshield, so glass service inevitably disturbs the camera's mounting position and requires subsequent recalibration to restore correct operation.
28. A — Temporary sun-glare sensitivity that briefly blinds the forward camera when the sun is directly in its field of view is a documented feature limitation of current camera technology. The camera cannot see through intense direct sunlight, and the feature becomes temporarily unavailable — this is not a hardware failure requiring replacement.
29. B — Lane keep assistance provides active steering input through the Electronic Power Steering Module, while lane departure warning only issues audible and visual alerts. The two features are distinct — LDW warns, LKA actively intervenes — and they can fail independently of each other despite sharing the forward camera as their common input.
30. D — A failed forward camera heater in cold weather typically produces camera fogging or icing that disables camera-dependent features until the vehicle warms up. The heater is designed specifically to prevent this condition; its failure manifests as feature unavailability in cold conditions, not as physical damage or unrelated system effects.
31. C — The 76 to 81 GHz band, commonly called 77 GHz automotive radar, is the current industry standard for ADAS radar applications. Higher frequency allows finer resolution with smaller antennas, which is why this band has become universal for modern long-range and short-range automotive radar design.
32. A — FMCW stands for Frequency-Modulated Continuous Wave. The transmitted signal continuously sweeps across a range of frequencies, which allows simultaneous measurement of range and velocity with relatively simple hardware. This is the dominant radar technique in automotive applications for its effective target tracking capability.
33. D — Adaptive cruise control at minimum requires input from the forward radar (for target distance and closing-rate data) and the ACC switch inputs on the steering wheel (for driver control of engagement and speed). These two input categories define the core ACC requirement — other sensors may enhance the feature but are not required for basic operation.
34. B — Non-OEM bumper covers with non-OEM paint in the radar zone may not meet the radar transparency specification required for the 77 GHz band. The materials can attenuate signal and degrade detection performance, which is why OEM position statements typically specify OEM parts in radar zones.
35. A — Corner radar modules on a typical ADAS vehicle primarily support blind spot warning (detecting vehicles in adjacent lane blind spots) and rear cross-traffic alert (detecting approaching traffic when backing up). These two features share the corner radar hardware and its private CAN bus on the composite vehicle architecture.

36. D — Silent miscalibration is most often caused by unverified preconditions during the calibration procedure — floor slope, vehicle loading, tire pressures, or target placement errors. These factors affect calibration geometry without triggering scan tool errors, so the procedure completes with incorrect parameters while reporting success.
37. C — OEM position statements are formal OEM guidance documents that define the standard of care expected of technicians performing ADAS-related repairs. They carry significant weight in insurance disputes and legal proceedings, and deviation from them exposes the shop to genuine liability regardless of whether the repair otherwise appeared successful.
38. D — After programming, coding, and initialization, calibration per OEM procedure is the final required step before delivery. Calibration establishes the module's geometric reference frame, which is essential for correct operation. Skipping this step leaves the module non-functional regardless of how well the earlier workflow steps were performed.
39. C — Automotive ultrasonic sensors operate at frequencies above the range of normal human hearing, typically 40 to 50 kilohertz. This ultrasonic frequency allows pulses that do not disturb occupants or pedestrians while providing adequate resolution for short-range distance measurement in parking applications.
40. A — Automotive ultrasonic sensors have a typical effective range of approximately 2 to 5 meters, making them suitable for low-speed maneuvering applications like parking and park pilot features. They are not designed for highway-speed detection or long-range applications beyond the vehicle's immediate perimeter.
41. C — Paint applied directly over an ultrasonic sensor's transducer face attenuates the ultrasonic signal dramatically and degrades or fails sensor operation. The paint physically impedes the sound energy that the transducer must transmit and receive, which is why OEM procedures require sensor removal before any bumper cover painting operation.
42. D — A single internally failed ultrasonic sensor is replaced individually, followed by scan tool verification of the new sensor's operation. No system-wide intervention (replacing every sensor, reprogramming the control module, replacing the bumper cover) is required for a routine single-sensor replacement with verified supply and ground.
43. C — Rear cross-traffic alert on a typical ADAS vehicle relies on the rear corner radar modules, which communicate over the private corner radar CAN bus. RCTA detects vehicles approaching from either side when backing up. Forward camera, ultrasonic sensors, and forward radar handle other ADAS functions, not the rearward cross-traffic detection that RCTA requires.
44. A — Cold-weather-only parking sensor failures with clean sensors in the warm shop strongly suggest ice or snow accumulation on transducer faces during cold driving that melts before shop arrival. This weather-correlated pattern is a documented environmental interaction, not a hardware failure or system limitation the customer should accept.

45. C — Water droplets on ultrasonic sensor transducer faces produce false echo returns during wet weather. The droplets reflect ultrasonic pulses back to the sensor, creating the illusion of nearby obstacles. This is a known environmental interaction that resolves when the sensor faces dry, and it is not a hardware failure requiring parts replacement.
46. B — Battery disconnection can cause various modules to lose learned data that must be re-established through specific initialization or relearn procedures per OEM service information. Checking these requirements is the productive first step — replacement, alignment, or reprogramming are premature responses to a condition that may only require a relearn procedure.
47. A — The post-repair scan's primary purpose is to verify which codes were cleared by the repair and identify any new codes introduced during service. This comparison to the pre-repair scan is foundational to repair verification documentation and demonstrates that the service resolved the original issues without creating new ones.
48. D — Operational verification after an ADAS repair primarily confirms that the repaired feature actually functions correctly under real-world conditions. Scan tool verification alone cannot confirm real-world operation — road testing the specific repaired feature in representative conditions is required for complete professional verification.
49. B — Customer handoff after ADAS service should include clear communication of what was repaired, what to expect, and the driver's continuing responsibility for safe vehicle operation. This sets correct expectations about feature limitations and protects both parties from misunderstanding about what the ADAS system provides.
50. A — ADAS repair documentation should be retained per shop policy for extended periods aligning with insurance and litigation timelines, typically 7 years or longer. These timelines can extend well beyond the repair date, and the documentation may be requested long after the original work — short retention periods create exposure the shop cannot afford.